



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 10

1200 Sixth Avenue, Suite 900
Seattle, WA 98101-3140

OFFICE OF
WATER AND WATERSHEDS

January 3, 2017

Jerry Allen, CEO
7 Cedars Resort
Jamestown S'Klallam Tribe
270756 Highway 101
Sequim, WA 98382

Re: Optimal Corrosion Control Treatment- **Copper Pipe Removal and Replacement Project**
7 Cedars Casino - PWS ID # 105300108

Dear Mr. Allen:

We have reviewed your final report of the Copper Pipe Removal and Replacement Project, which includes copper monitoring results from March 2015 through December 2016. We are pleased to inform you that the 7 Cedars Casino water system is now in compliance with the Lead and Copper Rule under the Safe Drinking Water Act.

In order to remain in compliance, your water system must collect ten samples for lead and copper for two consecutive six month monitoring periods: January 1, 2017 through June 30, 2017 and July 1, 2017 through December 31, 2017. During these monitoring periods, if lead levels remain low and copper levels no longer exceed the 90th percentile Action Level of 1.3 mg/L, then your water system will be placed on an annual monitoring schedule. However, if 90th percentile copper levels continue to exceed the Action Level, you will be required to continue alternative corrosion control treatment in addition to copper line replacement.

The Environmental Protection Agency has been working with State and Tribal partners to identify ways to strengthen implementation of the nation's drinking water programs, with a particular focus on the Lead and Copper Rule. We will be providing compliance assistance to help you address any issues you may have with lead and copper action level exceedances.

If you have any questions, please contact me at (206)553-2578 or duvil.ricardi@epa.gov.

Sincerely

A handwritten signature in blue ink, appearing to read "Ricardi Duvil".

Ricardi Duvil, Ph.D.
Lead and Copper Rule Manager

cc: Adam Baron, EPA Drinking Water Compliance Officer
Kristen Burgess, Project Officer - ESA Associates. INC.
Richard Moore, Indian Health Services
Ron Sather, Facilities Manager
Bill Laubner, Facilities Manager